

Notes Flora Estates - City Dump
Inspection 6-4-87 with Rick Ewald

Behind IPlace Bldg Center a liquid was running quite heavily into the Flood Control Channel. A cream colored scum was seen on top of the pool where it came from the under broken slabs of concrete. An odor of ~~rotting~~ septic material was noticed.

Water samples and a mud sample were collected at this site. A 5-gal. plastic can of "Industrial Degreaser" was retrieved here. It has 1-2 gallons of liquid in it.

We walked north just east of the power line. From the bank of the F.C.C. to a service road (a distance of a few hundred feet) uncovered old refuse was seen - bottles, rusting cans, plastic bottles, ~~cars~~ car parts, appliances, etc. Sample 2, a "soil" sample was collected along this route.

We continued across the service road, just east of the power line, and found standing water surrounded by tall grass and weeds. Sample #3 was collected here - liquid and a sediment sample.

Took pictures 1-17, 20

John Anderson