



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 7580228  
 SPILL NAME: SENECA LAKE TRIB. DEC LEAD: BWFINSTE  
 SPILL DATE: 02/17/1975 SPILL TIME: 2:15 pm  
 CALL RECEIVED DATE: 02/17/1975 RECEIVED TIME: 2:15 pm

### SPILL LOCATION

PLACE: SENECA LAKE TRIB. COUNTY: Schuyler  
 STREET: WELL WEST ROUTE 14 TOWN/CITY: Montour  
 COMMUNITY: WATKINS GLEN  
 CONTACT: \_\_\_\_\_ CONTACT PHONE: \_\_\_\_\_

CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Responsible Party  
 FACILITY TYPE: Commercial/Industrial WATERBODY: GROUND WATER

CALLER REMARKS:  
 PIPING BENT DUE TO AN ICE BUILD-UP AND DISTORTED THE PIPE (IN WELL #49) LEGAL ACTION PENDING 5311  
 (B)(5) VIOLATION - EPA.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
#2 fuel oil	Petroleum	1,500 G	0 G	GW,

### POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
INTERNATIONAL SALT	WATKINS GLEN NY 14891	JAMES LOOSE

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

### DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was "BF".

02/16/06: PAPER FILE REMOVED PER FILE RETENTION POLICY.

PIN                      T & A                      COST CENTER

CLASS: C3              CLOSE DATE: 02/17/1975              MEETS STANDARDS: True



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 9508880  
 SPILL NAME: AKZO SALT DEC LEAD: SARODABA  
 SPILL DATE: 10/17/1995 SPILL TIME: 12:00 pm  
 CALL RECEIVED DATE: 10/18/1995 RECEIVED TIME: 1:28 pm

### SPILL LOCATION

PLACE: AKZO SALT COUNTY: Schuyler  
 STREET: ROUTE 14 TOWN/CITY: Reading  
 COMMUNITY: READING  
 CONTACT: MARK COLE CONTACT PHONE: (607) 762-8294

CONT. FACTOR: Unknown SPILL REPORTED BY: Responsible Party  
 FACILITY TYPE: Unknown WATERBODY: ON LAND

### CALLER REMARKS:

WHILE NYSEG WAS DEVELOPING A GAS STORAGE THEY ENCOUNTERED CONTAMINATED SOIL THEY REMOVED ABOUT 200 YARDS OF SOIL.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
#2 fuel oil	Petroleum	0 G	0 G	Soil,

### POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
AKZO SALT	ROUTE 14 READING NY 14876	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

### DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was "SR".  
 10/18/95 ALTHOUGH APPROX 200 CU YDS OF CONTAMINATED SOIL HAVE BEEN REMOVED, CONTAMINATION IS STILL EVIDENT. RODABAUGH NOTIFIED 10/18 AT 1339 HRS.

10/19/95 SR INSPECTED; APPROXIMATELY 200-250 CU YDS OF SOIL EXCAVATED AND STAGED FOR DISPOSAL BY NYS ELECTRIC & GAS. CONTAMINATION CONTINUES ON WEST AND EAST, ZONE OF CONTAMINATION APPEARS TO BE 3-5 FT ZONE WITH NO APPARENT SOURCE. SAMPLES TAKEN FOR ANALYSIS, REPORT TO BE FORWARDED TO SPILLS. AT APPROX 5 FT, SOIL CLEAN PER NYSE&G, CONFIRMATORY SAMPLES TAKEN. AKZO SALT LIKELY RP FOR ADDITIONAL WORK. NYS E&G TO REVIEW LEASE AGREEMENT.

AKZO SALT HAS HIRED EMPIRE SOILS TO PERFORM SOIL BORINGS TO DELINEATE FUEL OIL CONTAMINATION. RESULTS TO BE FORWARDED TO SR.

PHASE II INVESTIGATION REPORT SUBMITTED 02/96. BASED ON RESULTS, NO FURTHER ACTIONS ARE NEEDED.

03/06/06: PAPER FILE REMOVED PER FILE RETENTION POLICY.

Created On: 10/19/1995

Date Printed: 9/19/2016

Last Updated: 03/06/2006



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 9508880  
SPILL NAME: AKZO SALT DEC LEAD: SARODABA

---

PIN

T & A

COST CENTER

CLASS: B3

CLOSE DATE: 05/29/1996

**MEETS STANDARDS:** False