



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

Identification Number 1 **EAST RESOURCES LEASE** **Spill Number: 0485712** **Close Date: 04/20/2005**
 NICHOLS RUN RD , NY NO ZIP PROVIDED

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
 Revised zip code: UNKNOWN

Source of Spill: COMMERCIAL/INDUSTRIAL Spiller: ED FIRDUKO – EAST RESOURCES Spiller Phone: 814-590-5060
 Notifier Type: DEC Notifier Name: Notifier Phone: ext. 6
 Caller Name: BRIAN JANDREW Caller Agency: NYSDEC Caller Phone: (716) 372-0645
 DEC Investigator: MXFRANKS Contact for more spill info: ED FIDURKO Contact Person Phone: (814) 590-5060

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
 Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
03/24/2005		EQUIPMENT FAILURE	YES		NO	

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	50.00	GALLONS	0.00	GALLONS	SOIL, SURFACE WATER

Caller Remarks:

lead line broke causing crude oil to flow into nichols run creek aoox 4000' away

DEC Investigator Remarks:

03/28/05: MF T/C ED FIRDUKO AFTER A CALL FROM MINERALS OF A SPILL THAT OCCURED 3/24/05. CLAIMED CREEK BOOMED & LINE REPAIRED. WHEN ASKED WHY SPILL WAS NOT REPORTED HE RESPONDED THAT IN PA IT DOSN'T HAVE TO. MEETING SCHEDULED FOR TOMORROW AT 1430.

03/29/05: MF S//ED FIDURKO, TIM WYMER, EAST RESOURCES. 2" LEAD LINE DEVELOPED LEAK APPX 12' BG. PIPE CLAMP INSTALLED. CRUDE FLOWED TO FEEDER TO NICHOLS RUN CREEK APPX 4000' AWAY. PIPE DAM INSTALLED, BOOM & PADS IN PLACE AT VARIOUS LOCATIONS. WATER VERY FAST & SILTY, MELT OFF THE LAST FEW DAYS. PIPE REPAIR EXCAVATION OPEN, WATER/CRUDE APPX 5' BG. TO BE PADDED. CHECKED BY LARRY MURPHY'S PROPERTY WHERE FEEDER GOES INTO NICHOLS RUN CREEK. UNABLE TO TELL IF ANY SHEEN, CREEK TOO FAST & MUDDY. NO ODOR NOTICED. WILL REINSPECT.

04/18/05: MF S//TIM, FOREMAN. CHECKED SPILL AREA. NO PRODUCT/SHEEN/ODOR NOTICED IN NICHOLS RUN CREEK. SEPARATOR FUNCTING, NO

PRODUCT/SHHEN. ALL THE PRODUCT HAS BEEN VACCED & PLACED IN THEIR STOCH TANK ALONG WITH WATER. THE WATER IS USED FOR THE INJECTION WELLS. MELT OFF & RAIN MADE FURTHER REMEDIATION NOT POSSIBLE. NO FURTHER ACTION NECESSARY.

*****COMPUTER FILE ONLY*****