



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

Identification Number 1

RESIDENTIAL PROPERTY
PHILLIPS HILL ROAD

Spill Number:
BOLIVAR, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14715

Source of Spill: PRIVATE DWELLING
Notifier Type: Affected Persons
Caller Name:
DEC Investigator: FXGALLEG

Spiller: UNKNOWN
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/11/2011		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
OTHER	OTHER	0.00	UNKNOWN	0.00	UNKNOWN	

Caller Remarks:

1118 THE CALLER ADVISED DISPATCH THE SPILL CAUSE IS UNKNOWN. THE CALLER STATED THE HOUSE IS OWNED BY HER PARENTS AND THEY HAVE DISCOVERED OIL IN THEIR TUB AND TOILET. UNKNOWN IF FRACKING COULD BE THE REASON. THE LOCATION OF THE RESIDENCE IS A FORMER OIL PLANT. THE CALLER HAS SPOKEN WITH DEC SPILLS IN REGION 9 WITHOUT GETTING ANY RESOLUTION. THE CALLER IS THREATENING TO SPEAK WITH THE MEDIA REGARDING THIS MATTER. THE CALLER IS INSISTING DEC RESPONDS IMMEDIATELY.

DEC Investigator Remarks:

9/11/11 FG SPOKE TO _____, CALLER. MS. _____ IS THE DAUGHTER OF THE PROPERTY OWNER. SHE SAID THAT HER PARENTS HAVE HAD OIL IN THEIR WELL WATER FOR THE LAST TWO AND 1/2 YEARS. SHE SAID THEY CALLED THE DEPARTMENT PREVIOUSLY, BRIAN JANDREW WITH MINERALS, AND HE DIDN'T DO ANYTHING. SHE SAID THEY ALSO NOTIFIED THE HEALTH DEPARTMENT AND THEY TOLD HER THAT IT WAS BACTERIA. HER PARENTS HAVE LIVED IN THE HOUSE FOR THE LAST TWENTY YEARS. I TOLD HER THAT I WOULD INSPECT THE PROPERTY ON MONDAY MORNING AND MS. _____ WAS SATISFIED WITH THAT.

9/12/11 FG SITE INSPECTION _____ PHILLIPS HILL RD, BOLIVAR. THE OWNERS, _____ AND _____ WITH THE WELLSVILLE _____ WERE AT THE PROPERTY. MR. _____ SHOWED ME HIS BATHROOM IN THE BACK CENTER OF THE HOME. AN OIL LAYER WAS PRESENT IN THE TOILET. OIL RESIDUAL WAS PRESENT IN THE BATHROOM SINK AND IN THE BATHTUB. MR. _____ SHOWED ME THE KITCHEN SINK AND WHEN RUNNING THE WATER, AN OIL ODOR WAS PRESENT. OIL RESIDUAL WAS PRESENT IN THE SINK. HE SHOWED ME THE OTHER BATHROOM

WITH THE SAME EVIDENCE.

WE LOOKED AT THE WATER WELL HEAD OUTSIDE IN BACK OF THE PROPERTY AND HE SAID THAT HE PAID A WATER WELL DRILLER TO CLEAN OUT THE WELL BUT THE OIL RETURNED. MR. SAID THE WELL IS 280 FEET DEEP AND THERE IS NO PRETREATMENT. HE SAID THERE IS A HOLDING TANK UNDER THE HOME AND IT IS DIFFICULT TO ACCESS. MR. SAID THAT HE HAS SEEN SHALE FRAGMENTS COMING IN WITH THE WATER AND OIL. MR. PURCHASES WATER FOR DRINKING. HE DOES USE THE WELL WATER FOR CLOTHES WASHING, DISH WASHING AND ALL BATHROOM NEEDS. HE SAID HE HAS BEEN THROUGH SEVERAL WASHING MACHINES. I ASKED WHY HE HASN'T DRILLED ANOTHER WELL AND HE SAID IT IS TOO EXPENSIVE. MR. MENTIONED THAT HE IS 84 YEARS OLD.

MR. SUGGESTED THAT THE CAUSE OF THE OIL IN HIS WATER MAY BE FROM FRACKING AND I TOLD HIM THAT IS NOT YET ALLOWED IN NEW YORK STATE AND HE SAID HE WAS AWARE OF THAT BUT THAT THE PENNSYLVANIA BORDER IS CLOSE BY AND IT COULD BE FROM THEM.

MR. & MRS. DID NOT BELIEVE THAT THE PROPERTY WAS AN OIL PLANT AS HAD BEEN MENTIONED IN THE INITIAL DISPATCH REPORT GIVEN TO THE NYSDEC HOTLINE. THEY BELIEVE THAT WAS WRITTEN IN ERROR.

I ASKED IF I COULD COLLECT A SAMPLE OF THE OIL IN THE BACK CENTER BATHROOM SINK AND HE AGREED. I RAN THE WATER AND THEN STOPPED UP THE SINK TO COLLECT A PRODUCT SAMPLE. I WAS ABLE TO COLLECT A PRODUCT SAMPLE FROM THE LAYER THAT WAS PRESENT AT 11:10 AM AND TOOK A PHOTO OF THE BATHROOM.

FG SPOKE TO MR. WITH THE WELLSVILLE AND TOLD HIM THAT WE WOULD ANALYZE THE OIL SAMPLE COLLECTED TO DETERMINE WHAT IT IS AND THEN HAVE A BETTER IDEA OF HOW TO INVESTIGATE FURTHER. I TOLD HIM THE RESULTS SHOULD BE BACK IN 10 DAYS.

I TOLD MR. & MRS. THAT WE WOULD PROVIDE THE RESULTS TO THEM WHEN WE RECEIVE THEM AND LET THEM KNOW WHAT THE NEXT COURSE OF ACTION WOULD BE. THEY REQUESTED THAT I CONTACT THEM AFTER 2PM TUES – FRI BECAUSE THEY WORK ON THOSE DAYS.

9/13/11 FG SPOKE TO CHARLES THROPP WITH MINERALS. HE SAID THE CLOSEST WELL IS APPROXIMATELY 1300 FEET AWAY FROM THE PROPERTY. THIS WELL WAS INSTALLED ON 11/12/1984 IS LABELED BY TURTLE OIL. IT IS NORTHWEST OF THE PROPERTY AND IS 1450 FEET DEEP. THE OTHER WELLS IN THE AREA HAVE NO INSTALL RECORDS BECAUSE THEY MUST HAVE BEEN INSTALLED PRIOR TO RECORD KEEPING.

MR. THROPP SAID THERE COULD BE VEINS OF OIL AS SHALLOW AS THIS WELL BUT THERE IS NOT ENOUGH AVAILABLE OIL FOR PRODUCTION. HE HAS NO INFORMATION SPECIFICALLY ON THIS AREA.

9/15/11 FG NOTIFIED TOM HULL WITH THE ALLEGANY COUNTY HEALTH DEPARTMENT OF THE SPILL REPORT.

9/20/11 FG RECEIVED THE ANALYTICAL RESULTS OF THE SAMPLE COLLECTED FROM THE BATHROOM SINK OF THE HOME. THE RESULTS SHOW THAT IT IS FUEL OIL #2 AND AN UNREFINED RAW PETROLEUM.

9/21/11 FG SPOKE TO MATT FORCUCCI WITH THE NYSDOH. HE PROVIDED THE FOLLOWING COMMENT ON THE ANALYTICAL REPORT: I got some feedback from various people with analytical backgrounds. The consensus is that it looks like a middle distillate fuel. Apparently, they think the lab used a fast temperature program that makes it more difficult to interpret the results, and they are interested in the results of the crude oil analysis for comparison, so if you could forward those results to me once you get them, I'll pass it on for further review.

9/21/11 FG SITE INSPECTION. MET AND THEIR DAUGHTER. PROVIDED A COPY OF THE ANALYTICAL RESULTS AND TOLD THEM THAT BECAUSE #2 FUEL OIL WAS DISCOVERED, THE DEPARTMENT CAN PROVIDE AN ALTERNATE WATER SUPPLY AND INVESTIGATE THE SOURCE. I TOLD THEM THAT IF THE INVESTIGATION SHOWS THAT THEY ARE RESPONSIBLE FOR THE SPILL THEN THEY WOULD HAVE TO PAY THE DEPARTMENT'S COSTS. THEY SAID THEY WILL THINK ABOUT THEIR OPTIONS AND CALL ME IF THEY WOULD LIKE THE DEPARTMENT TO DO THE WORK. THEY WILL SIGN THE RIGHT OF ENTRY PROVIDED IF THEY DO ALLOW THE DEPARTMENT ON SITE.

9/26/11 FG SITE INSPECTION. MET EMPIRE GEO ON SITE WITH ADAMS WELL DRILLING AND ROOT DRILLING. WE AGREED THAT THEY WOULD VIDEO INSPECT THE WELL TO DETERMINE IF THERE ARE ANY PROBLEMS. THE [REDACTED] GAVE ME THE SIGNED RIGHT OF ENTRY.

9/27/11 FG SITE INSPECTION. COLLECTED A SAMPLE OF CRUDE FROM THE LEASE OWNED BY [REDACTED] AT [REDACTED] PHILLIPS HILL RD, [REDACTED] BOLIVAR. TOOK SAMPLE TO TESTAMERICA AS A STANDARD TO COMPARE THE PREVIOUS SAMPLE COLLECTED FROM THE SINK AT THE [REDACTED] RESIDENT. MR. [REDACTED] WOULD LIKE A COPY OF THE RESULTS [REDACTED] EVANS AVE, BOLIVAR, NY 14715.

9/28/11 DAVE STEINER EMPIRE GEO NOTIFIED THE DEPARTMENT OF THE TWO BIDS HE RECEIVED FOR THE VIDEO INSPECTION AND WE CHOSE ROOT.

The quote from Root water Well Specialists is \$2,145.

The quote from Willey Well Drilling is \$3,600.

Services include:

- remove existing pump
- clean out the well and lower water level with larger temporary pump
- video the well's interior (and record)
- reinstall homeowner's pump, chlorinate/disinfect, and redevelop/pump clean

Root indicates they can get there sometime next week (week of October 3).

Willey indicates they can get there the week of October 10, maybe sooner if it is an emergency.

Even if Root needs 2 or 3 more hours at \$165/hour to complete everything, they are still well-below Willey.

David R. Steiner, P.G.

Environmental Services Manager

716-649-8110 office

716-649-8051 fax

716-359-5613 cell

10/4/11 TESTAMERICA SUBMITTED THE ANALYTICAL RESULTS FOR THE SAMPLE COLLECTED ON 9/27/11 AND THE RESULTS MATCH THE OIL SAMPLE COLLECTED FROM THE SINK OF THE RESIDENCE.

TESTAMERICA SUBMITTED THE ANALYTICAL RESULTS OF THE SINK SAMPLE ANALYZED FOR 8260 AND 8270. THE SAMPLE RESULTS SHOWED 4ISOPROPYLTOLUENE 1300 PPB, 135TRIMETHYLBENZENE 3300 PPB, NBUTYLBENZENE 1600 PPB.

10/5/11 FG SITE INSPECTION. [REDACTED] AND ROOT DRILLING ON SITE. VIDEO INSPECTED WELL AND FOUND NO PROBLEMS. SAMPLE COLLECTED FROM THE WELL TO BE ANALYZED FOR 8260 AND 8270 STARS LIST ANALYTES.

10/14/11 FG RECEIVED THE ANALYTICAL REPORT FOR THE CRUDE OIL SAMPLE ANALYZED FOR 8260 AND 8270. THE TOTAL 8260 RESULTS SHOW 12971000 PPB PRESENT. THE TOTAL 8270 RESULTS SHOW 89000 PPB PRESENT. THE DOH 310-13 WERE ALSO PROVIDED AND THE RESULTS SHOW FUEL OIL #2 TO BE PRESENT.

10/18/11 TESTAMERICA PROVIDED THE ANALYTICAL RESULTS FROM THE DRINKING WATER SAMPLE COLLECTED AT THE WELL ON SITE. THE RESULTS WERE NON DETECT FOR ALL ANALYTES.

11/8/11 EMPIRE GEO INDICATED THAT ROOT DRILLING WAS AVAILABLE TODAY AND WILL BE ON SITE TO DRILL THE WELL DEEPER TODAY. HE WILL BE ON SITE TODAY TO OVERSEE.

11/21/11 FG SPOKE TO [REDACTED]. THEY SAID THE WATER QUALITY AND VOLUME HAS IMPROVED BUT THEY STILL THINK THERE IS AN ODOR. THEY SAID ROOT WAS IN ON MONDAY AND CLEANED THE WATER LINES AND PRESSURE TANK OUT. I TOLD THEM WE WOULD COLLECT A WATER QUALITY SAMPLE AND THEY SAID WE CAN COME ANY DAY AFTER 2PM OR ANY TIME ON MONDAY.

11/21/11 FG CONTACTED DAVE STEINER WHO SAID HE WILL COLLECT THE WATER SAMPLE.

1/6/12 DAVE STEINER PROVIDED A COPY OF THE DRINKING WATER ANALYTICAL RESULT COLLECTED FROM THE WATER ON 11/22/11. THE RESULTS ARE NON DETECT FOR DOH 310-13, 8260 AND 8270 STARS. EMPIRE WILL SAMPLE THE DRINKING WATER QUARTERLY.

1/12/12 CALLED AND SAID THAT HER WATER SMELLS AND IS BLACK. SHE WANTED TO KNOW IF SHE BRINGS A GALLON OF WATER TO THIS OFFICE IF ANYONE WOULD DRINK IT. I TOLD HER WE WOULD GET THE RESULTS OF THE DRINKING WATER SAMPLE TO HER WHICH WERE ND AND HAVE ANOTHER SAMPLE COLLECTED.
FG NOTIFIED DAVE STEINER WITH EMPIRE TO COLLECT A SAMPLE.

1/31/12 FG RECEIVED THE TESTAMERICA RESULTS FOR SAMPLES COLLECTED FROM THE DRINKING WATER ON 1/16/12. THE RESULTS ARE ALL ND.

Identification Number 2

IN DRINKING WATER WELL

DAVIS HILL RD.

SCIO, NY 14880

Spill Number:

Close Date: 12/15/2010

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE

Revised zip code: NO CHANGE

Source of Spill: PRIVATE DWELLING

Notifier Type: Affected Persons

Caller Name:

DEC Investigator: FXGALLEG

Spiller:

Notifier Name:

Caller Agency:

Contact for more spill info:

Spiller Phone:

Notifier Phone:

Caller Phone:

Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
12/13/2010		UNKNOWN	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	0.00	GALLONS	0.00	GALLONS	GROUNDWATER

Caller Remarks:

CALLER STATES THAT THERE IS CRUDE OIL IN HIS DRINKING WATER WELL.

DEC Investigator Remarks:

12/13/10 FG SPOKE TO _____, PROPERTY OWNER. HE SAID ABOUT A WEEK AGO HIS DRINKING WATER WELL HAD A BROWN SUBSTANCE AND NO WATER. HE SPOKE TO SOME FRIENDS WHO SAID IT WAS OIL. HE CHANGED THE SUBMERSIBLE AND THE SAME OIL. HE SAID HIS SUBMERSIBLE WAS SET AT 160 FEET AND HE NOTICED WATER 45 FT UP FROM THE SUBMERSIBLE ON THE PIPE. HE ALSO WAS TOLD THAT MIDDAUGH **WAS PUMPING OFF OLD WELLS 3/4 MILE UP THE ROAD AND WAS TOLD TO STOP.**

FG NOTIFIED MINERALS AND THE ALLEGANY COUNTY HEALTH DEPARTMENT OF THE INCIDENT. CHRIS MILLER WITH MINERALS SAID HE WOULD SEND SOMEONE OUT TO THE AREA.

12/14/10 FG SITE INSPECTION. MR. _____ **HIRED A LOCAL WELL DRILLER WHO PUMPED OUT THE OIL.** WATER RETURNED AND MR. _____ IS HOOKING IT BACK UP. HE WILL LET US KNOW IF THE OIL RETURNS.

THE ALLEGANY CO HEALTH DEPT, ANNE KING AND TOM HULL WILL INSPECT THE PROPERTY.

NO FURTHER WORK BY SPILLS IS REQUIRED. THE SITE IS CLOSED.

ELECTRONIC FILE ONLY.

Identification Number 3

OVER BANK INTO CREEK
DRUM ROAD

Spill Number:
ALLENTOWN, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14707

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Other
Caller Name:
DEC Investigator: FXGALLEG

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/27/2011		DELIBERATE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
WASTE OIL/USED OIL	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	SOIL

Caller Remarks:

The following information was received from the complainant via e-mail either through the DEC public website Report an Environmental Violation Online page or directly to R5 dispatch mailbox:

Who Did It:

What Occurred: **DUMPING MATERIAL FROM OIL TANK OVERFLOW PIT OVER A BANK INTO A CREEK WHERE BEAVERS HAVE A DAM**

When Did It Occur:

County: Allegany

Municipality: ALLENTOWN NY

Location Or Address: CAN BE SEEN FROM MY LAND AT DRUN RD ALLENTOWN NY

How Did It Occur: **OPENED VALVE LET IT RUN !**

Complainants Name:

Complainants Phone:

Complainants Email:

Date of Submittal: 05/27/2011

DEC Investigator Remarks:

5/31/11 FG SITE INSPECTION. FG MET THE CALLER, WHO OWNS THE PROPERTY ADJACENT TO THE LEASE OPERATED BY . HE SAID ABOUT A WEEK PRIOR, THE LEASE OIL WATER SEPARATOR OVERFLOWED INTO THE STREAM WHICH LEADS TO THE GENESEE RIVER. DIRECTLY BELOW THE RELEASE FROM THE OIL WATER SEPARATOR FOR THE CRUDE OIL LEASE IS AN ACTIVE BEAVER DAM. FG MET ON SITE, THE LEASE HOLDER. HE SAID THE RELEASE WAS FROM A 5 GALLON BUCKET SITTING ON TOP OF THE BANK OF THE O/W SEPARATOR POND. I TOLD HIM THAT THERE WAS A LARGER SPILL THAN FROM A 5 GALLON BUCKET AND I POINTED OUT TO HIM THAT THERE WAS NO SEPARATOR PIPE AT THE DISCHARGE TO THE CREEK FROM THE O/W SEPARATOR POND. HE SAID IT WAS THERE YESTERDAY. HE DENIED THAT THERE WAS AN OIL SPILL. HE SAID THAT WHAT WAS ON THE GROUND WAS NOT CRUDE OIL AND HE SAID HIS PROPERTY WAS GRANDFATHERED IN AND DID NOT NEED A SPDES PERMIT. I TOLD HIM HE HAD TO REPAIR THE O/W SEPARATOR AND COMPLETE THE CLEANUP OF THE DISCHARGE.

E. NOTCH RD
BOLIVAR, NY 14715

6/14/11 FG SITE INSPECTION. ECO'S MARK WOJTOWIAK AND DON PLEAKIS ON SITE WITH , LEASE HOLDER. MR. PICKED UP SOME OF THE OIL ON THE GROUND AND PUT INTO BUCKETS AND A 50 GALLON DRUM. HE SAID HE WOULD DISPOSE OF THE CLEANUP MATERIAL. AN OIL WATER SEPARATOR (INVERTED PIPE) WAS PLACED IN THE POND THAT DISCHARGES TO THE CREEK.
cell

Identification Number 4 **ACROSS THE STREET ROAD** **Spill Number:** **Close Date:** **/2011**
 , NY NO ZIP PROVIDED

ADDRESS CHANGE INFORMATION
 Revised street: NO CHANGE
 Revised zip code:

Source of Spill: PRIVATE DWELLING Spiller: - ACROSS THE STREET FROM LEAK Spiller Phone:
 Notifier Type: Citizen Notifier Name: Notifier Phone:
 Caller Name: Caller Agency: Caller Phone:
 DEC Investigator: FXGALLEG Contact for more spill info: Contact Person Phone:

Category: Investigation indicates there was no spill.
 Class: Any Type of RP, Including No RP – DEC Field Response – Corrective Action Not Required or Not Possible

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
/2011		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	

Caller Remarks:
 crude oil leaking into the well – from old crude wells across the street – clean up pending

DEC Investigator Remarks:
 /2011: RJJ TELECON ,PROPERTY OWNER, SAID THAT FOR THE LAST 2 WEEKS, HAS HAD A PETROLEUM SHEEN & CRUDE OIL ODOR IN DRINKING WATER... IS LOOKING FOR ADVISE...I TOLD TO CALL THE ALLEGANY CO. HEALTH DEPT. & OUR DEC MINERAL DEPT.,FOR THEIR ADVISE AND TO INFORM THEM ABOUT THIS... SAID WILL...ALSO,FG WILL FOLLOW-UP ON THIS,AS NEEDED.
 /11 FG SPOKE TO TOM HULL WITH THE ALLEGANY COUNTY HEALTH DEPARTMENT. HE SAID THAT NOW HAS NO WATER IN WELL. THEY BELIEVE THAT THE LOSS OF WATER MAY BE CAUSED BY WELL PRODUCTION CLOSE BY AT A WELL OWNED BY . IT IS THE OPINION OF A LOCAL DRINKING WATER WELL DRILLER, THAT THE CAUSE OF THE LOSS OF WATER MAY BE A HOLE IN THE OIL PRODUCTION WELL CASING WHICH IS DRAWING ALL THE WATER AWAY. FG CONTACTED CHRIS MILLER WITH NYSDEC MINERALS. HE SAID HE WILL BE ABLE TO INSPECT THE WELL NEXT WEEK.
 /11 MINERALS DOES NOT BELIEVE THAT THE LOCAL WELL HAS ANY IMPACT ON THE WELL. THEY BELIEVE ALONG WITH THE LOCAL WELL DRILLERS THAT THE OIL IS NATURALLY OCCURRING AND MAY BE APPEARING DUE TO LOCAL DROUGHT CONDITIONS AND THERE IS CURRENTLY NO OIL. THE LOCAL WELL DRILLERS HAVE INDICATED THEY HAVE A LOW YIELD WELL. THERE HAVE BEEN NO FURTHER COMPLAINTS. SPILL IS CLOSED.

ELECTRONIC FILE ONLY.

Identification Number 5

HILLSIDE STREAM
NICHOLS RUN ROAD

Spill Number:
ALLEGANY, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14706

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/17/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	

Caller Remarks:

DUE TO INCREASE IN RUNOFF OLD PRODUCTION LINE HAD RESIDUAL GREASE/CRUDE FLOW OUT INTO WATERWAY ON HILLSIDE. BOOMS AND PADS WERE PLACED TO CATCH PETROLEUM BEFORE IT HIT NICHOLS RUN CREEK. WATER WAY WILL BE MADE TO COLLECTION POINT FOR REMEDIAL WORK TO BE COMPLETED. NO SHEEN IN CREEK.

DEC Investigator Remarks:

05/17/11 TDJ CONTACTED ME REGARDING SITUATION. HE HAD SEVERAL WORKERS IN SMALL WATERWAY MOPPING UP GREASY WASTE FROM OLD CRUDE LINE. COLLECTION DIKES WILL BE MADE TO HOLD BACK RESIDUAL GREASE FROM MOVING UNTIL PROBLEM WITH LINE IS RESOLVED.

Identification Number 6

HILLSIDE
NICHOLS RUN ROAD

Spill Number:
ALLEGANY, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14706

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
08/08/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	30.00	GALLONS	20.00	GALLONS	

Caller Remarks:

CALLER STATES THAT DEFECT IN ELBOW OF PRODUCTION LINE CAUSED A SPILL OF APPROX. 30 GALLONS OF CRUDE OIL ONTO SOIL. USEFUL CRUDE WAS COLLECTED FOR RECYCLE AND REMAINDER OF CONTAMINATED SOIL IS BEING PLACED INTO DRUMS.

DEC Investigator Remarks:

08/08/11 TDJ SPOKE WITH WHO STATED THAT CREW HAS BEEN CLEANING UP SINCE SPILL OCCURED. NO WATERWAY HAS BEEN IMPACTED.

08/10/11 TDJ INSPECTED SITE WHERE WORK IS IN PROGRESS TO CLEAN UP FROM LEAK IN LINE. LINE HAS BEEN CUT AND CAPPED BECAUSE THE WHOLE LEASE IS BEING PLUGGED AND CLOSED DOWN. INJECTION WELLS WILL BE REMOVED AND PLUGGED OVER A PERIOD OF TIME. LIQUID AND SOIL HAVE BEEN CONTAINED FROM THIS SPILL.

Identification Number 7

@ KORTWRIGHT RD
 @ KORTWRIGHT RD

Spill Number:
 BUSTI, NY NO ZIP PROVIDED

Close Date: 10/19/2011

ADDRESS CHANGE INFORMATION

Revised street: / KORTWRIGHT RD
 Revised zip code: 14701

Source of Spill: COMMERCIAL/INDUSTRIAL
 Notifier Type: Other
 Caller Name:
 DEC Investigator: TDJOHNSO

Spiller: - UNKNOWN
 Notifier Name:
 Caller Agency:
 Contact for more spill info:

Spiller Phone:
 Notifier Phone:
 Caller Phone:
 Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/02/2011		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled		Quantity Recovered		Resource(s) Affected
		Spilled	Units	Recovered	Units	
CRUDE OIL	PETROLEUM	70.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

Caller reporting a spill of 70 gallons of crude oil to ground. Notification Only

DEC Investigator Remarks:

09/02/11 TDJ WENT TO LOCATION LATER IN MORNING WHERE A CAR WENT THROUGH AN INTERSECTION INTO A FIELD WHERE (2) 5000 GALLON UPRIGHT CRUDE OIL STORAGE TANKS WERE LOCATED. THE CAR HIT THE SIDE OF ONE KNOCKING OFF THE FILL LINE CAUSING LEAKAGE OF CRUDE OIL RESULTING IN A FIRE. THE DRIVER FLED THE SCENE AND THE AUTO WAS BURNT UP ALONG WITH TREES AND BRUSH AROUND THE TANKS. SPILLAGE OF CRUDE WAS ESTIMATED AT 100 BARRELS BY WELL OWNER OF WHICH SOME SPREAD ON SOIL SURFACE WHILE BURNING UP AT THE SAME TIME. SPOKE WITH OWNER ABOUT CLEANUP AND DECIDED TO CONTACT NATIONAL VAC. SPOKE WITH TIM WHO HAD NO CREWS AVAILABLE UNTIL 9/6. DECIDED TO USE LOCAL BACKHOE OPERATOR TO SCRAPE SOIL SURFACE ONTO PILE FOR FUTURE DISPOSAL. AEREA WAS SCRAPED EXPOSING CLEAN LOOSE TOPSOIL WITH NO CONTAMINATION APPROX 3-5" BELOW SURFACE. SOIL WAS STAGED AWAY FROM SPILL AND WAS COVERED WITH POLY FOR DISPOSAL. VEHICLE WAS SUPPOSEDLY STOLEN FROM A HOUSE PARTY BUT INSURANCE CO. FOR VEHICLE WAS NOTIFIED OF ACCIDENT. WILL CONTACT NATIONAL GRID TO DISPOSE OF SOIL AND ALSO CONTACT INSURANCE FOR DISPOSAL.

09/07/11 TDJ MET TIM FROM NATIONAL VAC AND SITE OWNER TO COLLECT SAMPLE FOR DISPOSAL. PAYMENT WILL BE PAYED BY SITE OWNER BECAUSE INSURANCE WILL NOT PAY IF VEHICLE WAS STOLEN AND CAUSED THE DESTRUCTION OF PROPERTY.

SITE OWNER:

10/19/11 TDJ RECEIVED DISPOSAL RECEIPT FOR REMOVAL OF SOIL SCRAPED UP BY SITE OWNER. NATIONAL VAC CONTRACTED WITH SITE OWNER

TO DISPOSE OF SOIL AT LANDFILL.

NO FURTHER ACTION
FILE CLOSED

Identification Number 8

CONSTRUCTION SITE
OAKWOOD TERRACE

Spill Number:
ALLEGANY, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14706

Source of Spill: UNKNOWN
Notifier Type: Affected Persons
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/27/2011		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled		Quantity Recovered		Resource(s) Affected
		Units		Units		
CRUDE OIL	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	

Caller Remarks:

Caller stated that crude oil has shown up on several occasions flowing down drainage ditch from a house being constructed upgradient of his property. House has been under construction for at least one year.

DEC Investigator Remarks:

09/27/11 TDJ CONTACTED CALLER WHO STATED THAT ODOR AND APPEARANCE OF CRUDE HAS BEEN ONGOING. HE FINALLY DECIDED TO CALL FOR ASSISTANCE. WILL VISIT SITE TO DETERMINE IF POSSIBLE SOURCE.

09/28/11 TDJ WENT TO LOCATION AND OBSERVED PETROLEUM SHEEN IN DRAINAGE DITCH FLOWING FROM LIGHT RAIN IN FRONT OF CALLERS RESIDENCE. FOUND RESIDENCE BEING BUILT, WHICH LOOKS LIVED IN, AND FOLLOWED SHEEN TO A DISTURBED SOIL AREA UP ALONG STEEP SLOPED DRIVEWAY. IT APPEARS SOIL WAS EITHER DUG UP FROM SPILL OR SOMETHING WAS BURIED THERE AT ONE TIME. WENT TO DOOR BUT NO ANSWER. LEFT CARD TO CALL ME WHEN BACK AT RESIDENCE.

09/30/11 TDJ WAS CONTACTED BY OWNER REGARDING SOIL DISTURBED. , HOMEOWNER STATED THAT HE HAD NOTICED A SMALL AMOUNT OF OIL DURING RAIN EVENT SO DUG UP A SMALL AREA. I TOLD HIM TO DIG FURTHER TO TRY AND FIND THE EXTENT OF POSSIBLE SPILL. HE DUG UP AND FOUND AN OLD PRODUCT LINE FROM A CRUDE OIL WELL WHICH WAS OWNED BY THROPP DRILLERS . THE LINE WAS CAPPED BUT PRODUCT IN THE LINE MUST HAVE RELEASED WHEN A CAP IN THE END OF THE PLASTIC LINE CAME OFF. AFTER THE DIG RAIN CAUSED SOME CRUDE TO FLOW DOWN THE SLOPING DRIVEWAY INTO DEAD END ROADWAY DRAINAGE DITCH.

10/05/11 TDJ RECEIVED A COMPLAINT OF CRUDE OIL IN DRAINAGE DITCH. WENT TO LOCATION WHERE I HAD GREG THROPP MEET ME. HE HAD A WORKER COME TO HELP PUT PADS IN DITCH TO SOAK UP OIL. PUT BOOMS AT CULVERTS UNDER DRIVEWAYS TO CATCH OL IN POOLING AREAS.

10/06/11 TDJ WENT BACK TO LOCATION TO COLLECT OILY PADS. WATER HAD CLEARED AND ODOR OF CRUDE HAD DISIPATED. LET BOOMS IN PLACE TO CATCH RESIDUAL OIL FROM BANKS OF DITCH.

10/17/11 TDJ STOPPED AT LOCATION TO REPLACE BOOMS IF NEEDED. WATER WAS CLEAR IN DITCH SO REMOVED SOILED BOOM AND REPLACED ONE AT BOTTOM OF DRIVEWAY SLOPE. HOLE DUG AT BROKEN LINE AREA HAD WATER WHICH HAD NO SHEEN. CRUDE OIL SMELL HAD NEARLY DIMINISHED. WILL CHECK SITE TO SEE THAT DUG MATERIAL IS DISPOSED OF PROPERLY.

Identification Number 9

ROADSIDE DITCH
OAKWOOD TERRACE

Spill Number:
ALLEGANY, NY NO ZIP PROVIDED

Close Date: 10/06/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14706

Source of Spill: UNKNOWN
Notifier Type: Citizen
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
10/04/2011		UNKNOWN	NO		NO	

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SOIL, SURFACE WATER

Caller Remarks:

The property next to us has been under construction for a while. Today we notice that there is oil (and not a small amount) in the culvert in front of our house. We followed the trail to the property next door (Oakwood Terrace, Allegany). We've had a similar problem with this property and it's previous owners in the past and I believe the DEC was somehow involved in rectifying the situation.

Black heavy oil in the ditch. Active oil well leaked from same property several years ago. ? owns the lease.

DEC Investigator Remarks:

10/06/11 TDJ SPILL HAS BEEN ADDRESSED ON EARLIER COMPLAINT CALL. SEE SPILL #

Identification Number 10 **SOIL** **Spill Number:** **Close Date: 03/21/2011**
 PARKSIDE DR LIMESTONE, NY NO ZIP PROVIDED

ADDRESS CHANGE INFORMATION
 Revised street: NO CHANGE
 Revised zip code: 14753

Source of Spill: UNKNOWN Spiller: DRILLING Spiller Phone:
 Notifier Type: Other Notifier Name: Notifier Phone:
 Caller Name: Caller Agency: Caller Phone:
 DEC Investigator: FXGALLEG Contact for more spill info: ANONYMOUS Contact Person Phone:

Category: Investigation indicates there was no spill.
 Class: Willing RP – No DEC Field Response – Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/19/2011		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	

Caller Remarks:

Caller advised saw a large amount of unknown petroleum was running down a hill from a pipe that is protruding out of the hill.
 Caller advised there is a distinct and strong odor.

DEC Investigator Remarks:

3/20/11 FG SITE INSPECTION. COULD NOT LOCATE PIPE AND DID NOT SEE PETROLEUM AT THE ADDRESS GIVEN. COULD NOT CONTACT THE CALLER BECAUSE ANONYMOUS. NO FURTHER ACTION POSSIBLE. SITE CLOSED.

ELECTRONIC FILE ONLY

Identification Number 11

LEASE

Spill Number:
LIMESTONE, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14753

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
03/24/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	20.00	GALLONS	0.00	GALLONS	

Caller Remarks:

Break in underground line caused crude oil to surface on hillside. Line was shut down and downgradient area from surfaced material was dug up. Crew from is working on collecting water/crude collecting in dug pit. Liquids are being drummed and solids will be placed into container.

DEC Investigator Remarks:

03/25/11 TDJ WENT TO LOCATION WHERE BREAK IN UNDERGROUND CAUSED CRUDE TO FLOW DOWN GRADE OF HILL. EXCAVATION OF BROKEN LINE AND SCRAPING OF SURFICIAL CRUDE CONTAMINATION TO BE COMPLETED.

04/11/11 TDJ MET TO EXAMINE SURFICIAL SPILL AREA AFTER SNOWMELT WAS COMPLETE. ADDITIONAL WORK NECESSARY ON SURFACE ALONG PATH OF SURFACE FLOW.

04/27/11 TDJ EXAMINED CLEANUP OF SURFICIAL CONTAMINATION. EQUIPMENT WAS USED TO SCRAPE SOIL/LEAVES INTO ROLLOFF. NO VISUAL STAINING WAS EVIDENT ALONG PATH. CLEANUP WAS APPROVED TO CLOSE SPILL. AWAITING DISPOSAL INFO.

Identification Number 12

**PIPELINE RUPTURE
UPPER BIRCH RUN**

ALLEGANY, NY NO ZIP PROVIDED

Spill Number:

Close Date: 08/16/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14706

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: FXGALLEG

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended		
04/12/2011		EQUIPMENT FAILURE	NO	NO		
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	210.00	GALLONS	0.00	GALLONS	SOIL, SURFACE WATER

Caller Remarks:

pipeline rupture from a crude oil line. it got into a spring, about 1000 ft affected. spill is contained. vacuum truck is at the scene removing the product.

DEC Investigator Remarks:

4/12/11 BRIAN JANDREW WITH MINERALS INSPECTED THE SPILL. HE PROVIDED THE FOLLOWING COMMENTS. I checked out the spill reported on the upper birch run road. The operator has a crew of 12 working there. He has installed 6 siphon pits and three booms I would say that most of the oil has been stopped at the entrance to the lease and less than a gallon flowed downstream. I have photo's that I can send to you. I will follow-up tomorrow and let you know the progress. The operator has a vac truck removing the oil and putting the oil fluid into his separator tanks to ensure that all of the oil is recovered.

4/13/11 BRIAN JANDREW WITH MINERALS PROVIDED ANOTHER INSPECTION REPORT: Attached are photos and a map of the spill area. I walked the stream from the lease to the bridge crossing on the Road near Road. I didn't find any accumulation of oil. He had a crew of five men out there today cleaning up residual oil in the siphon areas. I will check the lease again week , but as of today i would a say that more than 98 % of the oil has been cleaned -up .

7/13/11 FG SPOKE TO WHO SAID THAT HE JUST RECEIVED THE ANALYTICAL RESULTS FROM MICROBAC ON THE CONTAMINATED SOIL. HE IS GETTING APPROVAL AT HYLAND IN ANGELICA AND WILL PROVIDE THE DISPOSAL RECEIPT WHEN THE WORK IS COMPLETED.

8/16/11 MR. PROVIDED THE DISPOSAL RECEIPT FOR THE CONTAMINATED SOIL. THE SPILL IS CLOSED.

Identification Number 13

LEASE WELL
NICHOLS RUN ROAD

Spill Number:
CARROLL, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14770

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
04/28/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	7.00	GALLONS	0.00	GALLONS	

Caller Remarks:

LEASE LINE BROKE CAUSING MINOR SPILLAGE OF CRUDE OIL. RAIN CAUSED MOVEMENT ON SOIL SURFACE. PADS USED TO SOAK UP FILM.

DEC Investigator Remarks:

04/28/11 TDJ WENT TO LOCATION WHERE WORKERS HAD SCRAPED SURFACE GRASS AND SOIL INTO DRUMS. SPILL WAS A SMALL AMOUNT SPREAD BY HEAVY RAINFALL. A SMALL BERM WALL WAS MADE AT END OF SPILL IN CASE MORE RAINFALL RUNS DOWN SLIGHT SLOPE. PADS WILL BE PLACED TO COLLECT ANY RESIDUAL. THIS SOIL/GRASS WILL BE PLACED IN THE ROLLOFF FROM EARLIER SPILL OF SIMILIAR CRUDE OIL FROM BREAK IN LINE.

Identification Number 14

SIPHON POND
NICHOLS RUN ROAD

CARROLL, NY NO ZIP PROVIDED

Spill Number:

Close Date: 08/29/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14770

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/07/2011		OTHER	NO	NO

Material Spilled	Material Class	Quantity Spilled		Quantity Recovered		Resource(s) Affected
		Units		Units		
CRUDE OIL	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	

Caller Remarks:

CALLER STATED THAT **DUE TO HEAVY RAINFALL AN OVERFLOW OF SIPHON HOLDING POND CREATED A FLOW OF CRUDE OIL DOWN HILLSIDE.** BARRIERS WERE CREATED TO CONTAIN SPILL.

DEC Investigator Remarks:

05/09/11 TDJ WENT TO LOCATION AND MET OIL FIELD PERSONS. **OVERFLOW OF A MOLASSESS CONSISTENCY CRUDE SLUDGE CREATED A THIN PATHWAY DOWN HILLSIDE** TO PRE DUG COLLECTION PIT WHERE CRUDE HAD FLOWED INTO. HEAVY EQUIPMENT WILL BE USED TO SCRAPED SOIL SURFACE UP TO POND. COLLECTED CRUDE WILL BE PUMPED INTO DRUMS. WORK PLAN IS BEING DEVELOPED TO CLOSE AND REMEDIATE POND.

06/14/11 TDJ WENT TO LOCATION WHERE HAS CONSULTANT REMOVING PIT SLUDGE BY THE TRUCKLOAD. SMALLER SIDE PIT WAS CLEANED FIRST TO PID READINGS <1.0 PPM. GRAVEL FROM HILLSIDE IS BEING USED TO REFILL EXCAVATION. LARGER PIT WILL BE COMPLETRED WHEN SMALL PIT AREA IS FILLED AND CAN BE USED FOR ACCESS TO LARGE PIT AREA ALONG HILLSIDE. PROJECT TO BE COMPLETE BY EARLY WEEK OF 6/20.

6/21/11 TDJ WENT TO LOCATION TO SEE SOIL REMOVAL COMPLETION. HILLSIDE STONE/DIRT WAS BEING USED TO FILL IN PIT ONCE PID READINGS SHOWED NEAR ND. SOIL WAS COLLECTED FROM SEVERAL LOCATONS FOR CONFIRMATORY RESULTS.

8/25/11 TDJ RECEIVED FINAL REPORT FOR CONTAMINATED SOIL DISPOSAL RECEIPTS AND CONFIRMATORY SSAMPLING RESULTS. LOW LEVEL TARGET COMPOUNDS WERE DETECTED IN A FEW SAMPLES BUT MAJORITY OF COUMPOUDS WERE NON-DETECT. THE PIT WAS COMPLETELY FILLED AFTER EXCAVATION WORK WAS COMPLETE.

NO FURTHER ACTION
FILE CLOSED

Identification Number 15

OIL FIELD ON NEIGHBORING PROPERTY
PINE RIDGE RD

Spill Number:
JAMESTOWN, NY NO ZIP PROVIDED

Close Date: 05/16/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14701

Source of Spill: PRIVATE DWELLING
Notifier Type: Affected Persons
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

(PROPERTY OWNER) Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
05/10/2011		HOUSEKEEPING	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	SOIL

Caller Remarks:

Subject that owns and operates small oil field is not maintaining the areas very well and there are areas of about 10' x 15' that the soil is soaked with oil. Caller states to drive down driveway to the newer beige barn and the location is to the right of the orange cone that was recently placed there.

DEC Investigator Remarks:

05/13/11 TDJ WENT TO LOCATION WHERE I SPOKE WITH WHO LEASES THE PROPERTY FOR CRUDE OIL PRODUCTION. HE STATED THAT HE KNEW OF AREA AND STSED THAT IT CAME UP FROM UNDERNEATH. HE DUG DOWN AND FOUND DRY DIRT WHICH I INSPECTED AND CONFIRMED. HE WAS GOING TO DIG WITH A BACKHOE TO TRY TO FIND PROBLEM. NO VISUAL PETROLEUM STAINING WAS OBSERVED ANYWHERE. WILL CONTACT ME WHEN A PROBLEM IS FOUND.

05/16/11 TDJ RECEIVED A CALL FROM WHO STATED THAT AREA WAS FOUND WHERE SMALL LEAK IN LINE WAS FOUND. LINE WAS REPAIRED AND MINIMAL AMOUNT OF IMPACTED SOIL WAS TAKEN TO AREA WHERE HE GENERATES CONTAMINATED SOIL FROM SMALL SPILLS FOR EVENTUAL PROPER DISPOSAL.

NO FURTHER ACTION
FILE CLOSED.

Identification Number 16

IN FORDS BROOK

FORDS BROOK ROAD SOUTH BRANCH

Spill Number:

WELLSVILLE, NY NO ZIP PROVIDED

Close Date: 05/16/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE

Revised zip code: 14895

Source of Spill: COMMERCIAL/INDUSTRIAL

Notifier Type: Citizen

Caller Name:

DEC Investigator: TDJOHNSO

Spiller:

Notifier Name:

Caller Agency:

Contact for more spill info:

Spiller Phone:

Notifier Phone:

Caller Phone:

Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
05/16/2011		OTHER	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SOIL, SURFACE WATER

Caller Remarks:

crude oil well leaking into creek. () Puddle of oil 3 foot diameter, went into ditch and then stream.

DEC Investigator Remarks:

05/16/11 TDJ CONTACTED MINERALS IN ALLEGANY AND SPOKE WITH BRIAN JANDREW. HE STATED THAT THE FLOODING CONDITIONS IN WELLSVILLE CAUSED THE OLD WELL FIELDS TO OVERFLOW IN SOME AREAS. HE ALSO KNEW THE COMPLAINANT AND WILL CONTACT HIM IF HE NEEDS FURTHER INFORMATION. SPILL IS REFERRED TO THE MINERALS OFFICE IN ALLEGANY.

NO FURTHER ACTION

FILE CLOSED TO ELECTRONIC ONLY

Identification Number 17

WELL
SOUTH MAIN STREET EXTENSION, NY NO ZIP PROVIDED

Spill Number:

Close Date: 01/30/2012

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: UNKNOWN

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Citizen
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known release which created a fire/explosion hazards (inside or outdoors), drinking water supply contamination, or significant releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/01/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled		Quantity Recovered		Resource(s) Affected
		Units		Units		
CRUDE OIL	PETROLEUM	200.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

LEAKING ABOVEGROUND PLASTIC TANK THAT'S INVOLVED WITH GAS WELL. SPILL OCCURED DURING THE WINTER. TANK HAS BEEN REPAIRED. ABSORBENT PADS WERE USED TO CLEAN UP BUT STAINED SOIL REMAINS. CONTAMINTION IS AROUND THE 1200 GALLON BRINE TANK AND THE 500 GALLON CRUDE OIL TANK.

DEC Investigator Remarks:

06/15/11 TDJ WENT TO LOCATION AND MET . HE SHOWED ME THE TWO PLASTIC HOLDING TANKS USED BY FOR CRUDE PRODUCTION. ONE OF THE TANKS HAD A GASKET FAIL ON THE DRAIN WHICH CAUSED IT TO SPILL IN A SOIL CONTAINMENT AREA. IT APPEARS THAT WOOD CHIPS WERE USED TO SOAK UP THE OIL BUT WAS NEVER CLEANED UP. I WILL CONTACT COMPANY FOR REMEDIATION OF SITE. THE LEASE HAS BEEN IN PLACE FOR < 1YEAR.

6/16/11 TDJ CONTACTED AT TO SET UP REMOVAL OF CONTAMINATED SOIL. REP. FROM CALLED BACK AND WILL GET CONTRACTOR TO REMOVE AND DISPOSE OF SPILL AREA. WILL CONTACT ME WHEN WORK BEGINS.

07/05/11 TDJ SPOKE WITH WHO STATED THAT THE WORKERS WERE ON SITE WITHIN 4 DAYS OF MY INSPECTION TO REMOVE THE SPILLED CRUDE. WORK WAS DONE TO THE SATISFACTION OF . I WILL CONTACT FOR DISPOSAL RECEIPT.

01/30/12 TDJ RECEIVED DISPOSAL RECEIPTS.

NO FURTHER ACTION
FILE CLOSED

Identification Number 18

LEASE.
BARNUM ROAD, NY NO ZIP PROVIDED

Spill Number:

Close Date: 09/19/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: UNKNOWN

Source of Spill: COMMERCIAL VEHICLE
Notifier Type: DEC
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/22/2011		HUMAN ERROR	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	20.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

Truck picked up oil. Oil spilled when disconnected on to road. is cleaning up now.

DEC Investigator Remarks:

06/23/11 TDJ SPOKE WITH ABOUT SPILL. PADS WERE USED TO SOAK UP AND SOIL SCRAPING NEAR EDGE OF ROAD STOPPED FLOW OF OIL. THEY WILL CONTINUE TO MONITOR SPILL SITE.

08/02/11 TDJ REVISITED SITE WHICH WAS CLEAN WITH NO RESIDUAL. MINIMAL AMOUNT OF CLEANUP MATERIAL WAS PLACED INTO COMPANY COLLECTION BIN FOR DISPOSAL.

NO FURTHER ACTION
FILE CLOSED TO ELECTRONIC ONLY

Identification Number 19

LEAKING WELL

COUNTY ROUTE 38

ALMA, NY NO ZIP PROVIDED

Spill Number:

Close Date: 07/21/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
 Revised zip code: 14708

Source of Spill: COMMERCIAL/INDUSTRIAL
 Notifier Type: Affected Persons
 Caller Name:
 DEC Investigator: TDJOHNSO

Spiller:
 Notifier Name:
 Caller Agency:
 Contact for more spill info:

Spiller Phone:
 Notifier Phone:
 Caller Phone:
 Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/01/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled		Quantity Recovered		Resource(s) Affected
		Units		Units		
CRUDE OIL	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

NEW OWNER OF WELL. NAME IS . BRAND NEW RIG ON WELL. LEAK WAS OBSERVED LAST MONTH BUT IT HAS GOTTEN WORSE AND WAS OBSERVED TO NOW BE SPUTTERING WITH A CONSTANT OOZE. NO CONTACT INFORMATION ON NEW OWNER.

DEC Investigator Remarks:

07/11/11 TDJ WENT TO LOCATION WHERE RESIDENT SHOWED ME THE PRESSURE LEAK ON THE WELL HEAD IN THEIR FRONT YARD. SMALL STREAM OF CRUDE OIL IS LEAKING DOWN WELL HEAD TO GROUND. MAKING THE YARD SMELL. RESIDENT DOES NOT HAVE THE NAME OF NEW OWNER OF WELL. I PLACED PADS AT BASE AND AT LEAK POINT TO CONTAIN CRUDE. WILL CONTACT CHRIS MILLER WITH MINERALS TO SEE IF OWNER OF WELL IS ON RECORD.

07/12/15 TDJ CHRIS MILLER FROM MINERALS CALLED TO STATE THAT WELL OPERATOR HAS BEEN CONTACTED AND WILL REPAIR LEAKING WELL HEAD. SOIL WILL BE SCRAPED AND DISPOSED IN GENERAL REFUSE COLLECTION. MINERALS WILL FOLLOW UP ON COMPLETION.

NO FURTHER ACTION
 FILE CLOSED TO ELECTRONIC ONLY

Identification Number 20

**ROADSIDE
PLANK ROAD WEST OF**

Spill Number:
WESTFIELD, NY NO ZIP PROVIDED

Close Date: 09/14/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14787

Source of Spill: COMMERCIAL VEHICLE
Notifier Type: Fire Department
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/20/2011		TRAFFIC ACCIDENT	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIESEL	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SOIL
BRINE	OTHER	0.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

Tanker truck roll over carrying brine, lost part of the brine load and nearly all the diesel. Clean up will be required. Company has been contacted they have not yet hired anyone to do the clean up. Spill contained with speedy dry and pads.

DEC Investigator Remarks:

07/20/11 TDJ WENT TO LOCATION WHERE TANK TRUCK WAS LYING ON IT'S SIDE. CAR RAN THROUGH STOP SIGN HITTING THE WHEELS CAUSING THE TRUCK TO ROLL OVER. TANK WAS HOLDING BRINE WHICH LEAKED A MINIMAL AMOUNT. THE SINGLE DIESEL SADDLE TANK LEAKED APPROX 20 GALLONS ONTO ROADWAY. SPEEDY DRY AND PADS PLACED BY THE FIRE DEPT. STOPPED THE FLOW IN ROADWAY. REMAINING DIESEL WAS PUMPED OUT BY WRECKER. TRUCK WAS UPRIGHTED AND TOWED AWAY. CHAUTAUQUA CO.EMERGENCY SERVICES CLEANED UP SPEEDY DRY AND PLACED INTO DRUM WHICH WAS TAKEN BACK TO COMMAND CENTER. WILL CONTACT OWNERS INSURANCE COMPANY TO SET UP DIRECT PAY TO NATIONAL VAC FOR DISPOSAL OF DRUM. ROADWAY WAS TO BE SANDED AND POWER SWEEP BY COUNTY HIGHWAY DEPT. CRACKS AND GOUGES IN ROAD TO BE REPLACED BY HIGHWAY DEPT.

09/13/11 TDJ RECEIVED DISPOSAL RECEIPT FROM NATIONAL VAC FOR PETROLEUM CONTAMINATED MATERIAL COLLECTED FROM SPILL SITE. MATERIAL WAS STAGED AT CHAUT. CO. HAZ MAT OFFICE IN MAYVILLE. SITE HAS BEEN CLEANED TO SATISFACTION OF DEPARTMENT.

NO FURTHER ACTION
FILE CLOSED

Identification Number 21

LEAKING CRUDE WELL
OFF OF HICKS HILL ROAD

Spill Number: WIRT, NY NO ZIP PROVIDED

Close Date: 08/31/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14739

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Other
Caller Name:
DEC Investigator: FXGALLEG

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended		
08/01/2011		OTHER	NO	NO		
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SURFACE WATER

Caller Remarks:

THE LANDOWNER, LOCAL STREAM, API #'S AND , CALLED MINERALS COMPLAINING THAT THERE IS A LEAKING WELL AND THE CRUDE IS DISCHARGING TO A TO THAT AREA WITH AND AND . MR. THROPP WILL INSPECT TODAY. FG SPOKE TO BRIAN JANDREW WHO SAID THAT HE WENT NEAR RECENTLY

DEC Investigator Remarks:

8/30/11 RECENTLY PURCHASED THIS PROPERTY LOCATED AT HICKS HILL ROAD. THIS IS THE SITE OF FORMER SPILL .

FG SPOKE TO CHARLES THROPP WITH MINERALS AND ON 8/29/11 HE INSPECTED THE SITE. HE FOUND THERE IS AN ARTESIAN WELL WHICH DISCHARGES TO AN OIL WATER SEPARATOR POND. HE DID NOT NOTICE ANY OIL DISCHARGING TO A WATERWAY. HE SAID THERE IS 8 TO 10 BARRELS OF GREASE ON TOP OF THE WATER. CHARLES THROPP PROVIDED AN UPDATE ON HIS SITE VISITS: DMN Region 9 received a complaint from August 29, 2011 about a spill. I inspected the site – I saw no oil entering the creek. I estimate ~ 8–10 BBL of heavy paraffin grease on the surface of the pond. See attached photos:

FG SPOKE TO WHO OWNS THE PROPERTY. HE DID NOT TAKE THE MINERAL RIGHTS. HE BELIEVES THE MINERAL RIGHTS OWNER IS AND HE BELIEVES HE LIVES IN SHINGLEHOUSE, PA. MR. WILL SEND THE LAST LEASE INFORMATION HE FOUND.

THE 1992 SPILL WAS CLOSED IN 1995 AFTER SOIL REMEDIATION WAS COMPLETED AND THE OIL WATER SEPARATOR WAS INSTALLED.

8/31/11 PROVIDED LEASE INFORMATION:
I found these names (owners Of C&G Oil) at the alleghany co. court house.

N. Main St. Wellsville Ny.

Scio Ny.

(This is the # Charles Called)

Osborn St.
wellsville Ny.

Chestnut St.
Wellsville Ny.

Chestnut St.
Wellsville Ny.

W. State St.
Olean Ny.

Scio Ny.

Friendship Ny.
the formation of C&G Oil co. was in 1948
All the Information I am finding about
He lives In Shingle House Pa.

FG SPOKE TO AND TOLD HIM THE DEPARTMENT WILL DO NO ADDITIONAL WORK BECAUSE THE POND IS AN OIL WATER SEPARATOR AND IS HOLDING THE OIL. HE WILL CONTACT MINERALS TO PURSUE CLOSURE OF THE WELLS ON HIS PROPERTY. THE SPILL IS CLOSED.

Identification Number 22

WELL SITE
SAGER ROAD

Spill Number:
ELLERY, NY NO ZIP PROVIDED

Close Date: 09/15/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: UNKNOWN

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
09/10/2011		HUMAN ERROR	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
HYDROCHLORIC ACID	HAZARDOUS MATERIAL	21.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

Opened wrong valve. Put soda ash over spillage. 32% HCL. Callers cell is . He would like a call to discuss clean up.

DEC Investigator Remarks:

09/12/2011 – GPS: Spill does not qualify for ECL 17–1743 Notification. No notification made.

09/12/11 TDJ WENT TO LOCATION WHERE WAS TOLD A TANKER TRUCK TRANSFERING MURIATIC ACID HAD A RELEASE OF APPROX. 20 GALLONS TO GRAVEL FLAT YARD. ANOTHER 30 GALLONS OF WATER WAS RELEASED WITH IT CAUSING IT TO FLOW FOR APPROX. 50'. BAGS OF SODA ASH WERE PLACED ON SPILL TO NEUTRALIZE MATERIAL AND A LAYER OF SANDY GRAVEL WAS PLACED OVER THAT. THE pH OF THE ACID IS 1.5 IN SOLUTION. HAD MSDS SENT TO OFFICE FOR REVIEW.

9/14/11 TDJ WENT BACK TO SITE WHERE I MET OPERATIONS WORKERS. SEVERAL SHALLOW TEST PITS WERE DUG USING A SHOVEL TO CHECK THE pH OF THE SOIL. FOUR OF SIX OF THE PITS SHOWED pH AT 7–8 WHILE THE OTHER TWO WERE AT pH 5–6. SAMPLING SHOWED THAT ACID WAS NEUTRALIZED TO AN ACCEPTABLE LEVEL TO CLOSE OUT SPILL.

NO FURTHER ACTION
FILE CLOSED

Identification Number 23

LEASE
CHIPMUNK ROAD

Spill Number:
ALLEGANY, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14706

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/21/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	55.00	GALLONS	0.00	GALLONS	

Caller Remarks:

Caller stated that stuffing box on well head leaked approx. one barrel of crude onto soil. Cleanup underway.

DEC Investigator Remarks:

11/22/11 TDJ SPOKE WITH WHO STATED THAT APPROX 3/4 OF LIQUID WAS RECOVERED AND PADS AND BOOMS WERE PLACED INTO ANOTHER DRUM. SOIL SCRAPING CLEANED UP THE REMAINDER OF THE MATRERIAL.

Identification Number 24

HOME/NEIGHBORHOOD
PENNSYLVANIA AVE

Spill Number:
FRIENDSHIP, NY NO ZIP PROVIDED

Close Date: 11/29/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14739

Source of Spill: INSTITUTIONAL, EDUC, GOV, OTHER
Notifier Type: Other
Caller Name:
DEC Investigator: FXGALLEG

Spiller: UNK-PIPE
Notifier Name:
Caller Agency:
Contact for more spill info: CALLER

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Investigation indicates there was no spill.
Class: Any Type of RP, Including No RP – DEC Field Response – Corrective Action Not Required or Not Possible

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
11/28/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
OTHER	OTHER	0.00	UNKNOWN	0.00	UNKNOWN	AIR

Caller Remarks:

CALLER STATES THAT THERE IS A **LEAKING GAS LINE SOMEWHERE IN HIS MOTHERS NEIGHBORHOOD**, ALERTED THE LOCAL UTILITY COMPANY WHO SAID THEY WERE AWARE AND THAT REPAIRS WERE SHCEDULED, BUT CALLER IS CONCERNED FOR POTENTIAL HAZARDS THE CONTINUALLY LEAKING GAS MAY PRESENT. REQUESTING CALL.

DEC Investigator Remarks:

11/29/11 FG SPOKE TO WHO CALLED REGARDING THE ODOR OF NATURAL GAS AT HIS MOTHERS NEIGHBORHOOD. HE IS CONCERNED THAT THERE IS A SAFETY AND HEALTH HAZARD. FG CONTACTED NATIONAL FUEL WHO INDICATED THEY ARE AWARE OF THE RELEASE AND DEEM IT NOT AN EMERGENCY SITUATION. THEY WILL ADDRESS IT WHEN THEY GET TO IT ON THEIR REGULAR REPAIR SCHEDULE – THE DATE WAS UNKNOWN. FG SPOKE TO RON DEITZ WITH NATIONAL FUEL. FG CALLED MR. BACK AND TOLD HIM THEY DO NOT CONSIDER THE RELEASE AN EMERGENCY AND HE WAS SATISFIED. NO FURTHER ACTION NECESSARY. SITE IS CLOSED.

ELECTRONIC FILE ONLY.

Identification Number 25

CHIPMUNK ROAD

LEASE

Spill Number:
ALLEGANY, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14706

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Responsible Party
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/12/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	20.00	GALLONS	0.00	GALLONS	

Caller Remarks:

Caller states that release of crude inside of tank battery to containment. Soil will be scraped where affected. No release to waterways.

DEC Investigator Remarks:

12/12/11 TDJ SPOKE WITH WHO STATED CLEANUP IS IN PROGRESS. WILL INSPECT AFTER CLEANUP IS COMPLETE.

12/12/11 TDJ WENT TO LOCATION WHERE LEAK IN STORAGE TANK VALVE CREATED SPILL OF CRUDE. OIL WAS CONTAINED IN SMALL AREA WHERE SOIL AND STONE WAS BEING SCRAPED INTO DRUMS FOR DISPOSAL. THREE ADDITIONAL STORAGE TANK IN BATTERY WILL HAVE THEIR VALVES CHANGED FOR PREVENTATIVE MEASURES.

Identification Number 26

LEASE
NORTH CORTWRIGHT ROAD

Spill Number:
BUSTI, NY NO ZIP PROVIDED

Close Date: 12/28/2011

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14701

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: DEC
Caller Name:
DEC Investigator: TDJOHNSO

Spiller:
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non-petroleum/non-hazardous spills.
Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
12/14/2011		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	20.00	GALLONS	20.00	GALLONS	SOIL

Caller Remarks:

plastic line broke lost 20 gallon crude. collected and put back in process tank. Mineral will look and call back

DEC Investigator Remarks:

12/28/11 TDJ SPOKE WITH BRIAN JANDREWS OF MINERALS WHO STATED THAT HE CHECKED CLEANUP WHICH WAS COMPLETE. MINOR AMOUNT WAS REMOVED FROM SOIL AND WAS TAKEN BACK TO SHOP FOR DISPOSAL.

NO FURTHER ACTION
FILE CLOSED TO ELECTRONIC ONLY

Identification Number 27

OFF PARKSIDE DRIVE

Spill Number:

CARROLLTON, NY NO ZIP PROVIDED

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
 Revised zip code: 14753

Source of Spill: COMMERCIAL/INDUSTRIAL
 Notifier Type: Responsible Party
 Caller Name:
 DEC Investigator: TDJOHNSO

Spiller:
 Notifier Name:
 Caller Agency:
 Contact for more spill info:

Spiller Phone:
 Notifier Phone:
 Caller Phone:
 Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/04/2012		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	20.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

Checked well at 7 am it was ok, checked again at 2 pm, found about 20 gallons near the well head. Well shut down and cleanup has begun. Will fix tomorrow morning. Chris Miller contacted already.

DEC Investigator Remarks:

01/05/12 TDJ SPOKE WITH WHO STATED CLEAN UP IS COMPLETE AND WAS CONTAINED IN A SMALL DEPRESSION NEAR WELL. CONTAMINATED SOIL WAS EXCAVATED AND WILL BE TAKEN FOR DISPOSAL AT LANDFILL. DISPOSAL RECEIPT WILL BE SENT WHEN ACCEPTED.

Identification Number 28

INDIAN CREEK ROAD , NY NO ZIP PROVIDED

Spill Number:

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
 Revised zip code: UNKNOWN

Source of Spill: COMMERCIAL/INDUSTRIAL
 Notifier Type: DEC
 Caller Name:
 DEC Investigator: TDJOHNSO

Spiller:
 Notifier Name:
 Caller Agency:
 Contact for more spill info:

Spiller Phone:
 Notifier Phone:
 Caller Phone:
 Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
01/17/2012		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	300.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

Valve broke at tank,

DEC Investigator Remarks:

01/17/12 RMC/BRIAN JANDREWS/PHONE. 5 PERSON CREW WORKING ON CLEAN UP. MINERAL TO INSPECT THIS AM.

01/17/12 TDJ MET BRIAN JANDREW (MINERALS) AND AT LOCATION. VALVE ON CRUDE OIL HOLDING TANK WAS FOUND OPEN AT APPROX. 7:00AM ON 1/17 BY WORKER. CRUDE WHICH IS CONSTANTLY HEATED FLOWED OUT OF PIPE INTO RESERVIOR AND DOWN DIRT ROAD DITCH ALONG FIELDS. BACKHOE WAS USED TO CREATE PONDS TO COLLECT CRUDE. OIL IN RESERVOIR WAS BEING PUMPED BACK INTO TANK. ESTIMATE OF APPROX. 900 GALLONS WAS RELEASED OF WHICH AN ESTIMATE OF 600 GALLONS COLLECTED NEAR TANK. WE DECIDED TO USE A WATER TRUCK TO WASH CRUDE OUT OF SNOW AND ICE ON ROAD AND DITCH. WATER FLOWED INTO PONDS WHERE WATER WAS DIVERTED PAST WITH PUMP AND UNDER WATER PIPE OVERFLOW SYSTEM PUT IN. OIL WILL BE PUMPED OUT OF PONDS AND PLACED BACK INTO TANK. WORK WILL CONTINUE FOR THE REST OF WEEK TO REMOVE CRUDE FROM FROZEN SURFACE. WHEN DIRT AND STONE DRIVE THAW A MACHINE WILL REMOVE CONTAMINATED MATERIAL UNDER SURFACE. OTIS EASTERN OWNS THE FIELDS WHICH CRUDE FLOWED ONTO. CRUDE WAS NOT NEAR ANY WATERWAYS LEADING OFFSITE.

1/18/12 TDJ SPOKE WITH REGARDING PROGRESS ONSITE. HE STATED COLLECTION AREA NEAR TANK WAS PUMPED OUT COMPLETELY WHICH WAS APPROX. 50 GALLONS. HE SAID ANOTHER 100-150 GALLONS WAS COLLECTED FROM LOWER DUG PITS. STATED SITE LOOKS MUCH BETTER AND SURFACE WAS FROZEN FROM CHANGE IN TEMP. I WILL RE-INSPECT LATER IN WEEK.

1/26/12 TDJ WENT TO LOCATION AND FOUND TANK HAS BEEN MOVED AND SOIL WAS EXCAVATED TO CLEAN AROUND SPILL AREA. MOST OF SNOW AND ICE HAD MELTED AND SURFACE WATER WAS FLOWING INTO ONE OF THE COLLECTION PITS FOR OIL REMOVAL. MOST OF THE ODOR OF CRUDE HAD DISIPATED AND SHEEN WAS CLEARING UP ON ROADWAY. WILL CHECK WHEN WEATHER DRIES UP.

Identification Number 29

UNKNOWN ODOR

HILLSIDE / INTERSECTION

Spill Number:
LIMESTONE, NY NO ZIP PROVIDED

Close Date: 02/08/2012

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 14753

Source of Spill: UNKNOWN
Notifier Type: Federal Government
Caller Name:
DEC Investigator: TDJOHNSO

Spiller: - UNKNOWN
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
02/07/2012		UNKNOWN	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
CRUDE OIL	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	

Caller Remarks:

States that the caller advises them that there is a smell of crude oil in the area of above.

DEC Investigator Remarks:

02/07/12 TDJ CONTACTED [REDACTED] OF [REDACTED] OIL AND GAS WHO ARE LOCATED NEAR [REDACTED] HILLSIDE DRIVE. HE WAS CONTACTED BY NEW RESIDENT FOR CRUDE OIL ODOR AND WAS OUTSIDE AS I SPOKE WITH HIM. THE ODOR IS MORE PREVALENT WHEN THE AIR IS HEAVY DURING WINTER MONTHS. HE STATED THAT THE ODORS ARE FROM THE TANK BATTERIES LOCATED NEAR THAT LOCATION. LONG TIME RESIDENTS ARE FAMILIAR WITH THE ODORS AND ARE LESS AFFECTED. WILL SPEAK WITH COMPLAINANT AND CHECK AIR WHEN IN AREA.

02/07/12 TDJ WENT TO LOCATION LATER IN DAY. SPOKE WITH [REDACTED] WHO SHOWED ME THE TANK STORAGE AREA WHICH HAD A CRUDE OIL SMELL. NO VISIBLE STAINING NOR SIGNS OF SPILLAGE WAS EVIDENT. WIND CONDITIONS WERE IN A DIRECTION SENDING ODORS TO SEVERAL NEARBY RESIDENCES. [REDACTED] WILL MONITOR THE CONDITION FOR POSSIBLE WAYS TO LIMIT ODORS.

NO FURTHER ACTION
FILE CLOSED TO ELECTRONIC ONLY