



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**SUNRISE FRANKLIN CORP**  
181 SOUTH FRANKLIN AVENUE

VALLEY STREAM, NY NO ZIP PROVIDED

**Spill Number: 9609102**

**Close Date:**

ADDRESS CHANGE INFORMATION  
Revised street: NO CHANGE  
Revised zip code: 11580

Source of Spill: **GASOLINE STATION**  
Notifier Type: DEC  
Caller Name: BRIAN CAMPBELL  
DEC Investigator: JLPITKEW

Spiller: N/A - SUNOCO OIL  
Notifier Name: NASSAU CTY HEALTH  
Caller Agency: NYS DEC  
Contact for more spill info: MR MAURICE RUBIN

Spiller Phone:  
Notifier Phone: (516) 571-2288  
Caller Phone: (516) 444-0320  
Contact Person Phone:

Spill Class: KNOWN RELEASE THAT CREATES POTENTIAL FOR FIRE OR HAZARD;DEC RESPONSE;WILLING RP;CORRECTIVE ACTION TAKEN

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
10/21/1996		UNKNOWN	<b>NO</b>	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
<b>GASOLINE</b>	PETROLEUM	0.00	GALLONS	0.00	GALLONS	<b>GROUNDWATER</b>
<b>MTBE (METHYL-TERT-BUTYL ETHER)</b>	HAZARDOUS MATERIAL	0.00	UNKNOWN	0.00	UNKNOWN	

Caller Remarks:

GASOLINE CONTAMINATED GROUND WATER WAS BACKING UP THRU BASEMENT SUMP PITS DUE TO GAS VAPORS IN BUILDING FIRE DEPT EVACUATED 6 STORY BUILDING.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was "AUSTIN WELL"  
SUN HIRED GTI & F&N TO PUMP OUT THE BASEMENT, BLDG VENTILATION SYSTEMS

12/12/00 FILE REASSIGNED

2/9/05 FILE REASSIGNED

4/4/08 FILE REASSIGNED

NYSDEC FALL 1998 MTBE SURVEY INFORMATION FOR 9609102

Maximum MTBE concentration: 81000.0 PPB  
 BTEX offsite: No

Current MTBE concentration: 2700.0 PPB

Source of MTBE

Number of private drinking water wells impacted: 0  
 Number of public water supply wells impacted: 0  
 Number of private drinking water wells impacted: 0  
 Number of replacement wells drilled: 0  
 Number of water main extensions: 0  
 Number of water main hookups: 0  
 Number of residences provided w/ bottled water: 0  
 Number of people affected: 0

Steel Underground Storage Tank -  
 Fiberglass Underground Tank -  
 Aboveground Storage Tank -  
 Piping -  
 Source not identified - X  
 Other source -

Indoor Air Impacts : Yes  
 Aquifer Impacts : Yes

Ongoing remediation: Yes

Monitoring Frequency

Monthly - Quarterly - X Semi-annual - Annual - Other -

Remedial Action used

No Action -

Groundwater

Soil

Pump and Treat - X  
 Air sparging - X  
 Bioreactor -  
 Natural attenuation -  
 Oxygen injection -  
 Biosparging -  
 Dual phase extraction -  
 Other -

Soil Vapor extraction - X  
 Excavation and disposal - X  
 Bioremediation -  
 Low temp thermal desorption -  
 Oxygen injection -  
 Other -

Under investigation: Yes

Dept. of Health involvement: Yes

-----  
 Dept. of Health Remarks: No remarks given for this spill  
 -----

General Remarks: No remarks given for this spill