



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

Identification Number 1 **US SALT CORPORATION** **Spill Number: 0270552** **Close Date: 02/05/2003**
 3580 SALT POINT ROAD WATKINS GLEN, NY 14891

ADDRESS CHANGE INFORMATION
 Revised street: NO CHANGE
 Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL VEHICLE Spiller: UNKNOWN Spiller Phone:
 Notifier Type: DEC Notifier Name: Notifier Phone:
 Caller Name: SCOTT RODABAUGH Caller Agency: NYSDEC Caller Phone: (607) 739-0809
 DEC Investigator: SARODABA Contact for more spill info: BOB TRAVERS Contact Person Phone: (607) 535-2067 ext: 220

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.
 Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
02/04/2003	02/05/2003	OTHER	YES		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
DIESEL	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SURFACE WATER

Caller Remarks:

DURING AN INSPECTION PERFORMED DURING TANK CLOSURE ACTIVITIES, SR NOTED HEAVY, FAIRLY NARROW BAND OF PETROLEUM SHEEN IN SENECA LAKE, SOURCE OF SPILL INTO LAKE TRACKED TO US SALT SPDES OUTFALL. FURTHER INVESTIGATION FOUND SHEEN WAS CAUSED BY DISCHARGE FROM AN UNKNOWN VEHICLE THAT APPARENTLY WAS LEAKING DIESEL, OR SIMILAR MATERIAL, TO PARKING LOT. RUNOFF FROM RAINS GOING INTO STORMWATER DRAIN, CARRYING HEAVY SHEEN INTO OUTFALL. PADS AND SOME SPEEDY DRY USED TO MITIGATE MOST OF DISCHARGE. ADDITIONAL ACTIONS NOT NECESSARY.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was SR